

#### **Lecture 11 - Outline**

- LQG
- 2 Tuning the LQG controller
- Robustness of LQG
- 4 Integral action, reference values

3/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control




#### The separation principle

In LQG control, the optimal state feedback and the optimal observer are independent and can be designed separately.

- ullet The optimal state feedback gain L is independent of the state uncertainty
  - $\tilde{x}$  is zero-mean Gaussian  $\Rightarrow$  using  $u = -L\hat{x}$  is optimal
- The optimal Kalman filter gain K is independent of the control objective
  - From the Kalman filter's view, *u* is deterministic and does not affect the state uncertainty



# **Optimal output feedback - LQG**



Plant: 
$$\begin{cases} \dot{x} = Ax + Bu + w_1 \\ y = Cx + w_2 \end{cases} \Phi_w = \begin{pmatrix} R_1 & R_{12} \\ R_{12}^T & R_2 \end{pmatrix}$$

Controller: 
$$\begin{cases} \frac{d}{dt}\hat{x}(t) = A\hat{x}(t) + Bu(t) + K[y(t) - C\hat{x}(t)] \\ u(t) = -L\hat{x}(t) \end{cases}$$

Minimize 
$$E|z|^2 = E(x^TQ_1x + 2x^TQ_{12}u + u^TQ_2u)$$

5/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



# **Summary of LQG**

Given white noise  $\binom{w_1}{w_2}$  with intensity  $\binom{R_1}{R_{12}^T} \frac{R_{12}}{R_2}$  and the linear plant

$$\dot{x}(t) = Ax(t) + Bu(t) + w_1(k)$$
$$y(t) = Cx(t) + w_2(t)$$

consider controllers of the form

$$\dot{\hat{x}}(t) = A\hat{x}(t) + Bu(t) + K(y(t) - C\hat{x}(t))$$
  
$$u(t) = -L\hat{x}(t)$$

The stationary variance

$$E(x^TQ_1x + 2x^TQ_{12}u + u^TQ_2u)$$

is minimized when

$$L = Q_2^{-1}(SB + Q_{12})^T K = (PC^T + R_{12})R_2^{-1}$$
  

$$0 = Q_1 + A^T S + SA - (SB + Q_{12})Q_2^{-1}(SB + Q_{12})^T$$
  

$$0 = R_1 + AP + PA^T - (PC^T + R_{12})R_2^{-1}(PC^T + R_{12})^T$$

The minimal variance is  $tr(SR_1) + tr[PL^T(B^TSB + Q_2)L]$ 



#### Example - LQG control of an integrator

Consider the problem to minimize  $E(Q_1x^2 + Q_2u^2)$  for

$$\begin{cases} \dot{x}(t) = u(t) + w_1(t) \\ y(t) = x(t) + w_2(t) \end{cases} \qquad \Phi_w = \begin{bmatrix} R_1 & 0 \\ 0 & R_2 \end{bmatrix}$$

$$\Phi_w = \begin{bmatrix} R_1 & 0 \\ 0 & R_2 \end{bmatrix}$$

The observer-based controller

$$\begin{cases} \frac{d}{dt}\hat{x}(t) = A\hat{x}(t) + Bu(t) + K[y(t) - C\hat{x}(t)] \\ u(t) = -L\hat{x}(t) \end{cases}$$

is optimal with K and L computed as follows:

$$0 = Q_1 - S^2/Q_2 \implies S = \sqrt{Q_1Q_2} \implies L = S/Q_2 = \sqrt{Q_1/Q_2}$$
  
 $0 = R_1 - P^2/R_2 \implies P = \sqrt{R_1R_2} \implies K = P/R_2 = \sqrt{R_1/R_2}$ 

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### How to choose the cost function

- Only in rare instances does a quadratic cost function follow directly from the design specifications
- In most cases, the cost function must be iteratively tuned by the designer to achieve the desired closed-loop behavior


Some possible starting points:

- Only penalize the outputs y = Cx and the inputs u; put  $Q_1 = C^T C$ ,  $Q_2 = \rho I$ , and  $Q_{12} = 0$
- Make the diagonal elements equal to the inverse value of the square of the allowed deviations:

$$Q_{1} = \begin{pmatrix} \frac{1}{(x_{1}^{\max})^{2}} & \cdots & 0 \\ \vdots & \ddots & \\ 0 & \frac{1}{(x_{n}^{\max})^{2}} \end{pmatrix}, Q_{2} = \begin{pmatrix} \frac{1}{(u_{1}^{\max})^{2}} & \cdots & 0 \\ \vdots & \ddots & \\ 0 & \frac{1}{(u_{n}^{\max})^{2}} \end{pmatrix}, Q_{12} = 0$$



#### The LOG controller



The controller transfer function (from -y to u) is given by

$$C_{LQG}(s) = L(sI - A + BL + KC)^{-1}K$$

Same order as the plant model

Several options in Matlab:

- $\bullet$  L = lgr(..), K = lge(..), C LOG = reg(P.L.K)
- L = lgr(..), obs = kalman(..), C\_LQG = lggreg(obs,L)
- $\bullet$  C LOG = lag(P.O.R)

Automatic Control LTH, 2018 Lecture 11 FRTN10 Multivariable Control



#### **Tuning the cost function**


- To achieve higher bandwidth (more aggressive control), decrease  $Q_2$  or increase  $Q_1$
- To increase the damping of a state  $x_j$ , add penalty on  $\dot{x}_i^2$
- (Advanced) To make a state  $x_i$  behave more like  $\dot{x}_i = -\alpha x_i$ , add penalty on  $(\dot{x}_i + \alpha x_i)^2$

Note that

$$\dot{x}_{j}^{2} = (A_{j}x + B_{j}u)^{T}(A_{j}x + B_{j}u)$$
$$= x^{T}(A_{j}^{T}A_{j})x + 2x^{T}(A_{j}^{T}B_{j})u + u^{T}(B_{j}^{T}B_{j})u$$



# **Example - LQ control of flexible servo**



$$m_1 \frac{d^2 y_1}{dt^2} = -d_1 \frac{dy_1}{dt} - k(y_1 - y_2) + F(t)$$

$$m_2 \frac{d^2 y_2}{dt^2} = -d_2 \frac{dy_2}{dt} + k(y_1 - y_2)$$

13/38


Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### **First iteration**


Minimize E  $(y_2^2 + u^2) = E(x^T(C_2^TC_2)x + u^2)$ 



Too fast—control signal too aggressive

#### **Open-loop response**

Response to impulse input disturbance:



14/38


Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### **Second iteration**

Minimize E  $(x^T (C_2^T C_2)x + 100u^2)$ 




Good speed, needs improved damping



#### Third iteration

#### Minimize

$$\mathrm{E}\left(y_2^2 + 0.1\dot{y}_2^2 + 100u^2\right) = \mathrm{E}\left(x^T(C_2^TC_2 + 0.1(C_2A)^T(C_2A))x + 100u^2\right)$$



#### Better damping, but more aggressive control signal

17/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### **Robustness of LQG controllers**

#### **Guaranteed Margins for LQG Regulators**

JOHN C. DOYLE

Abstract-There are none.

#### INTRODUCTION

Considerable attention has been given lately to the issue of robustness of linear-quadratic (LQ) regulators. The recent work by Safonov and Athans [1] has extended to the multivariable case the now well-known guarantee of 60° phase and 6 dB gain margin for such controllers. However, for even the single-input, single-output case there has remained the question of whether there exist any guaranteed margins for the full LQG (Kalman filter in the loop) regulator. By counterexample, this note answers that question; there are none.

[IEEE Transactions on Automatic Control, 23:4, 1978]

# 100 C S 11 V S

#### **Tuning the Kalman filter**

- The real noise properties are seldomly known
- As a starting point put  $R_1 = BB^T$ ,  $R_2 = \rho I$ ,  $R_{12} = 0$
- If the controller is too sensitive to measurement noise, increase  $R_2$  or decrease  $R_1$
- ullet If the robustness of the closed loop degrades too much when using the Kalman filter for output feedback, decrease  $R_2$  or increase  $R_1$

18/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### **Example (Doyle & Stein, 1979)**

Benign minimum-phase SISO plant (no fundamental limitations):

$$A = \begin{pmatrix} -4 & -3 \\ 1 & 0 \end{pmatrix}, \quad B = \begin{pmatrix} 1 \\ 0 \end{pmatrix}, \quad G = \begin{pmatrix} 61 \\ -35 \end{pmatrix}, \quad C = \begin{pmatrix} 1 & 2 \end{pmatrix}$$

$$Q_1 = 80 \begin{pmatrix} 1 & \sqrt{35} \\ \sqrt{35} & 35 \end{pmatrix}, \quad Q_2 = 1, \quad R_1 = 1, \quad R_2 = 1$$


gives

• Control poles:  $-7 \pm 2i$ 

• Observer poles:  $-7.02 \pm 1.95i$ 



#### **Example (Doyle & Stein, 1979)**



 $M_s = 4.8, \, \varphi_m = 14.8^{\circ}$ 


22/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### Doyle & Stein's example with LTR



1666

### **Loop transfer recovery**

The robustness of an LQG controller can often be improved by either

- ullet adding a penalty proportional to  $C^TC$  to  $Q_1$
- adding a penalty proportional to  $BB^T$  to  $R_1$

Makes the loop transfer function more similar to the state feedback (LQ) loop gain

Price: Higher controller gain, more amplification of noise

23/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



# Integral action via explicit integration

Add explicit integrators  $\dot{x}_i = r - y$  to track reference values without error.

Gives extended plant model

$$\begin{pmatrix} \dot{x} \\ \dot{x}_i \end{pmatrix} = \begin{pmatrix} A & 0 \\ -C & 0 \end{pmatrix} \begin{pmatrix} x \\ x_i \end{pmatrix} + \begin{pmatrix} B \\ 0 \end{pmatrix} u + \begin{pmatrix} 0 \\ I \end{pmatrix} r + \begin{pmatrix} I \\ 0 \end{pmatrix} v_1$$

Extended state feedback law from LQ design:

$$u = -\begin{pmatrix} L & L_i \end{pmatrix} \begin{pmatrix} x \\ x_i \end{pmatrix}$$

Including a penalty on  $x_i$  in the LQ design makes  $y \to r$  in case of a constant load disturbance or step reference change

(Matlab: lqi, lqgtrack, lqg)

24/38


Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



# Linear-quadratic-integral control in Matlab

lgi computes an optimal state-feedback control law for the tracking loop shown below. For a plant SYS with state-space equations dx/dt = Ax + Bu, y = Cx + Du, the state-feedback control is of the form u = -K[x; xi] where xi is the integrator output.



[K,S,E] = lqi(SYS,O,R,N) calculates the optimal gain matrix K given a state-space model SYS of the plant and weighting matrices Q,R,N. The control law u = -K z = -K [x;xi] minimizes the cost function


$$J(u) = Integral \{z'Qz + u'Ru + 2*z'Nu\}$$

27/38

Automatic Control LTH, 2018 Lecture 11 FRTN10 Multivariable Control



#### **LQG** example - Control of DC-servo



Process:  $P(s) = \frac{20}{s(s+1)}$ 

Cost function:  $J = E(z^2 + u^2)$ 

White noise intensities:  $R_1 = 1$ ,  $R_2 = 1$ ,  $R_{12} = 0$ 



#### Reference handling without integration

Simple solution using feedforward from r:

$$u(t) = -L\hat{x}(t) + L_r r(t)$$

Assuming we want to achieve y = r, select (for a square plant)

$$L_r = [C(BL - A)^{-1}B]^{-1}$$

to ensure static gain I from r to y

A reference filter to further shape  $G_{vr}(s)$  can be added if needed

28/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



# LQG design

State-space model (ignoring r):

$$\begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \end{bmatrix} = \begin{bmatrix} 0 & 0 \\ 1 & -1 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} + \begin{bmatrix} 20 \\ 0 \end{bmatrix} u + \begin{bmatrix} 20 \\ 0 \end{bmatrix} v_1$$

$$y = \begin{bmatrix} 0 & 1 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} + v_2 \qquad z = x_2$$

Cost matrices:

$$Q_1 = C^T C = \begin{bmatrix} 0 & 0 \\ 0 & 1 \end{bmatrix} \qquad Q_2 = 1$$

Solving the Riccati equations gives the optimal controller

$$\dot{\hat{x}} = (A - BL - KC)\hat{x} + Ky$$


$$u = -L\hat{x}$$


where


$$L = \begin{bmatrix} 0.2702 & 0.7298 \end{bmatrix} \qquad K = \begin{bmatrix} 20.0000 \\ 5.4031 \end{bmatrix}$$




#### **Gang of four**









 $\frac{P}{1+PC}$  reveals poor low-frequency disturbance rejection


31/38


Automatic Control LTH, 2018


Lecture 11 FRTN10 Multivariable Control




### Gang of four with integral action









#### Integral action

Add explicit integrator  $\dot{x}_i = r - y$  and extend the model:

$$\begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \\ \dot{x}_i \end{bmatrix} = \begin{bmatrix} 0 & 0 & 0 \\ 1 & -1 & 0 \\ 0 & -1 & 0 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \\ x_i \end{bmatrix} + \begin{bmatrix} 20 \\ 0 \\ 0 \end{bmatrix} u + \begin{bmatrix} 20 \\ 0 \\ 0 \end{bmatrix} v$$

Minimization of  $\mathrm{E}\left(x_2^2+0.01x_i^2+u^2\right)$  gives the optimal state feedback

$$u = -L_e \begin{bmatrix} \hat{x} & x_i \end{bmatrix}$$

where

$$L_e = \begin{bmatrix} 0.2751 & 0.7569 & -0.1 \end{bmatrix}$$

We can use the same Kalman filter as before  $(x_i \text{ is known})$ 

32/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### Matlab code for DC-servo example

```
A = [0 \ 0; \ 1 \ -1];
B = [20; 0];
G = [20; 0];
C = [0 \ 1];
sys = ss(A,B,C,0);
Q1 = C'*C;
Q2 = 1;
R1 = 1;
R2 = 1;
%% Design LOG controller
L = lqr(A,B,Q1,Q2)
                           % Calculate LQ feedback gain
K = lqe(A,G,C,R1,R2)
                           % Calculate Kalman gain
ctrl = -reg(sys,L,K);
                           % Form LQG regulator
```



### Matlab code for DC-servo example, cont'd

%% Design LQG controller with integral action, version 2
Qi = 1;
ctrl\_i2 = lqg(sys,blkdiag(01,02),blkdiag(G\*R1\*G',R2),Oi)


35/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### Alternative norms for optimization



Common alternative:  $H_{\infty}$  optimal control:

Minimize 
$$\sup_{\omega} \|G_{zw}(i\omega)\|$$

Can be solved using a couple of Riccati equations, similar to the LQG problem (Matlab: hinfsyn)



#### **Summary of LQG**

#### **Advantages**

- Works fine with multivariable models
- Observer structure ties to reality
- Always stabilizing
- Well developed theory, analytic solutions

#### **Disadvantages**

- Requires detailed state-space model
- Produces high-order controllers (same order as plant model)
- Sometimes hard to choose design weights
- No robustness guarantees must always check the resulting controller!
- Quadratic criterion ( $H_2$ ) not always the most suitable design requirement

36/38

Automatic Control LTH, 2018

Lecture 11 FRTN10 Multivariable Control



#### **Lecture 11 - summary**

- LQG design can produce a stabilizing controller for any controllable and observable linear MIMO plant
- Cost function and noise model must be tuned to obtain the desired closed-loop performance
  - Remember to respect fundamental limitations
- No robustness guarantees always check the result!

Next section of the course: Optimization of controllers using numerical methods

37/38 Automatic Control LTH, 2018 Lecture 11 FRTN10 Multivariable Control 38/38 Automatic Control LTH, 2018 Lecture 11 FRTN10 Multivariable Control